US EPA ARCHIVE DOCUMENT

Weekly Progress Summary

Delmont, PA

Photos

Text

Carbondale, Illinois

SES Job No.

E-717

© Copyright 2006, Sevenson Environmental Services, Inc.
All rights reserved

Distribution:

Mike Slenska
Mark Gravelding
Mason Wheeler
Les Halliday
Ben Huggins
Carolyn Bury

Weekly Project Summary No.

71

Work Performed Dates:

September 4 - 10, 2006

Photo 1

LOADING A HEAVY HAULER ONTO THE TRAILER FOR DEMOB

Photo 2

PLACING PROTECTIVE COVER ON THE G.C.L. FOR THE JOB SHUT-DOWN

Photo 3

GRADING THE OUTSIDE EDGE OF THE BORROW PIT ALONG THE NORTH EDGE

Photo 4

HYDRO SEEDING THE TYPE II COVER OF THE FORMER PROCESS AREA SURFACE COVER

Photo 5

COMPLETING THE MULCHING OF THE HYDRO SEEDED AREAS

Photo 6

INSTALLING THE SILT FENCE ALONG THE BOTTOM OF THE CAMU CAP

Text

General Comments:

THIS WEEKS SUMMARY OF WORK ACTIVITIES INCLUDE:

CAMU

* **COMMENCED INSTALLING SILT FENCE ALONG THE CAP**

MISCELLANEOUS

* **COMMENCED SURVEYING OF THE ON SITE ACCESS ROADS**
* **COMMENCED HYDRO SEEDING OF RELOCATION OF GLADE CREEK AND THE FORMER PROCESS AREA SURFACE COVER SOUTH OF THE CAMU**
* **CONTINUING TO CLEAN EQUIPMENT FOR DEMOB**
* **CONTINUING TO EXAMINE AND MAINTAIN EROSION AND SEDIMENTATION CONTROLS**
* **CONTINUING TO DO PERIODIC WORK SITE AIR MONITORING TO INSURE NO ACTION LEVELS ARE EXCEEDED**