

US EPA ARCHIVE DOCUMENT




FIGURE 2-1, JUNE/JULY 1996
 SUBSURFACE SOIL BORING LOCATIONS
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SEDS PROJECT No. 96S-058, JUNE 1997





FIGURE 2-2, JUNE 1996
SHALLOW TEMPORARY WELL LOCATIONS
REMEDIAL INVESTIGATION REPORT
NORTH BELMONT PCE SUPERFUND SITE
NORTH BELMONT, GASTON COUNTY, NC
SESD PROJECT No. 96S-058, JUNE 1997




LEGEND

- LOT NUMBERS
- ◆ TOP OF BEDROCK MONITORING WELLS
- ◆ BEDROCK MONITORING WELLS



FIGURE 2-3, TOP OF ROCK TEMPORARY WELLS AND PERMANENT MONITORING LOCATIONS, JULY/AUGUST 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997




● SURFACE WATER/SEDIMENT SAMPLE
201-88/90

SCALE
0 250 500
(IN FEET)
1 INCH = 500 FEET



FIGURE 2-4, JUNE 1996
 SURFACE WATER/SEDIMENT SAMPLE LOCATION
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997



SOURCE: DeLORME MAP EXPERT

FIGURE 2-5 BIOASSESSMENT SITES, UNNAMED TRIBUTARY-A
REMEDIAL INVESTIGATION REPORT
NORTH BELMONT PCE SUPERFUND SITE
NORTH BELMONT, GASTON COUNTY, NC
SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE



- SAMPLE LOCATION
- ★ SITE LOCATION



SOURCE: DeLORME MAP EXPERT

● SAMPLE LOCATION



FIGURE 2-6 REFERENCE SITE, DUTCHMANS CREEK
REMEDIAL INVESTIGATION REPORT
NORTH BELMONT PCE SUPERFUND SITE
NORTH BELMONT, GASTON COUNTY, NC
SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE