

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of continuing geotextile liner installation on Interim Cap No. 1 area. Photograph taken facing southeast.

FRAME NUMBER: 11 **DATE:** 26 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:50 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300071



SCENE: View of cover fill being delivered to Interim Cap No. 1 area. ERRS personnel check grade stakes and elevations. Photograph taken facing east.

FRAME NUMBER: 12 **DATE:** 26 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:52 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300071

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of ERRS personnel measuring grade elevations in Interim Cap No. 1. Note cover fill deliveries in background. Photograph taken facing southeast.

FRAME NUMBER: 13 **DATE:** 26 October 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta **SETTING:** Automatic

TIME: 10:53 **SKY CONDITION:** Sunny

WITNESS(ES): None

FILM TYPE: 35-mm **FILM ROLL:** BC300071



SCENE: View of construction activities in eastern section of Interim Cap No. 1. Photograph taken facing southeast.

FRAME NUMBER: 14 **DATE:** 26 October 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta **SETTING:** Automatic

TIME: 14:30 **SKY CONDITION:** Sunny

WITNESS(ES): NA

FILM TYPE: 35-mm **FILM ROLL:** bC300071

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of cover fill being distributed and graded in the southern section of Interim Cap No. 1. Photograph taken facing south.

FRAME NUMBER: 15 **DATE:** 26 October 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta **SETTING:** Automatic

TIME: 14:31 **SKY CONDITION:** Sunny

WITNESS(ES): None

FILM TYPE: 35-mm **FILM ROLL:** BC300071



SCENE: View of construction activities in Interim Cap No. 1. Photograph taken facing south.

FRAME NUMBER: 16 **DATE:** 26 October 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta **SETTING:** Automatic

TIME: 14:35 **SKY CONDITION:** Sunny

WITNESS(ES): None

FILM TYPE: 35-mm **FILM ROLL:** BC300071

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of cover fill being graded at ground level. Photograph taken facing east.

FRAME NUMBER: 17 **DATE:** 28 October 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta

SETTING: Automatic

TIME: 10:10

SKY CONDITION: Sunny

WITNESS(ES): None

FILM TYPE: 35-mm

FILM ROLL: BC300071



SCENE: View of cover fill being distributed and graded at ground level. Photograph taken facing southeast.

FRAME NUMBER: 18 **DATE:** 28 October 1999

PHOTOGRAPH BY: Renata Wynnyk

CAMERA: Minolta

SETTING: Automatic

TIME: 10:12

SKY CONDITION: Sunny

WITNESS(ES): None

FILM TYPE: 35-mm

FILM ROLL: BC300071

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of rip-rap stone cobbles being distributed along the Woonasquatucket riverbank. This portion of riverbank defines the western edge of Interim Cap No. 1. Photograph taken facing southwest.

FRAME NUMBER: 19 **DATE:** 2 November 1999

TIME: 08:30 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300071



SCENE: View of rip-rap being placed on riverbank. Leaf-fall is obscuring the geotextile liner beneath the rip-rap. Photograph taken facing south.

FRAME NUMBER: 20 **DATE:** 2 November 1999


TIME: 08:35 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of base fill being distributed in Interim Cap No. 2 area. Note residential property located on the Johnston, Rhode Island side of the Woonasquatucket River. Photograph taken facing west.

FRAME NUMBER: 21 **DATE:** 2 November 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 08:40 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300071



SCENE: View of construction activities in Interim Cap No. 1 area. Photograph taken facing southwest.

FRAME NUMBER: 22 **DATE:** 2 November 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 09:03 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300071

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of the eastern edge of Interim Soil Cap No. 1, with compacted cover fill in place. Photograph taken facing southeast.

FRAME NUMBER: 23 **DATE:** 2 November 1999

TIME: 09:03 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300071



SCENE: View of Interim Cap No. 1 with compacted cover fill. Photograph taken facing south.

FRAME NUMBER: 24 **DATE:** 2 November 1999

TIME: 09:06 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300071