

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of abandoned play area (tree fort), at the southern portion of proposed Interim Cap No. 1 area. Photograph taken facing east.

FRAME NUMBER: -- **DATE:** 2 September 1999
PHOTOGRAPH BY: Peter Welch
CAMERA: -- **SETTING:** Automatic

TIME: 12:35 **SKY CONDITION:** Sunny
WITNESS(ES): Renata Wynnyk
FILM TYPE: 35-mm **FILM ROLL:** --




SCENE: View of abandoned drum, located west of drainage channel area. Note heavy underbrush. Photograph taken facing north.

FRAME NUMBER: -- **DATE:** 2 September 1999
PHOTOGRAPH BY: Peter Welch
CAMERA: -- **SETTING:** Automatic

TIME: 12:37 **SKY CONDITION:** Sunny
WITNESS(ES): Renata Wynnyk
FILM TYPE: 35-mm **FILM ROLL:** --

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of tree clearing activities in proposed Interim Cap No. 1 area. Note sample location stake in foreground. Photograph taken facing east.

FRAME NUMBER: -- **DATE:** 2 September 1999
PHOTOGRAPH BY: Peter Welch
CAMERA: -- **SETTING:** Automatic

TIME: 12:31 **SKY CONDITION:** Sunny
WITNESS(ES): Renata Wynnyk
FILM TYPE: 35-mm **FILM ROLL:** --




SCENE: View of tree clearing activities in proposed Interim Cap No. 1 area. Note sample location stake in right foreground. Photograph taken facing northwest.

FRAME NUMBER: -- **DATE:** 2 September 1999
PHOTOGRAPH BY: Peter Welch
CAMERA: -- **SETTING:** Automatic

TIME: 12:30 **SKY CONDITION:** Sunny
WITNESS(ES): Renata Wynnyk
FILM TYPE: 35-mm **FILM ROLL:** --

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island

TOP



SCENE: View of emerging sinkhole, located at the former tailrace, on the Brook Village property. Note partial view of buried brick material inside the sinkhole. Photograph taken facing west.

FRAME NUMBER: 02 **DATE:** 14 September 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 14:45 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100365



SCENE: View of emerging sinkhole, located at the former tailrace, on the Brook Village property. Photograph taken facing north.

FRAME NUMBER: 03 **DATE:** 14 September 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 14:47 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100365

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of partially cleared area of Interim Cap No. 1. Note the Woonasquatucket River at the extreme right. Photograph taken facing south.

FRAME NUMBER: 07 **DATE:** 15 September 1999

TIME: 10:35 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk


WITNESS(ES): None

CAMERA: Minolta

SETTING: Automatic

FILM TYPE: 35-mm

FILM ROLL: BC100365



SCENE: View of clearing/wood chipping activities at the eastern portion of Interim Cap No. 1. Photograph taken facing south.

FRAME NUMBER: 08 **DATE:** 15 September 1999

TIME: 10:36 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta

SETTING: Automatic

FILM TYPE: 35-mm

FILM ROLL: BC100365

TOP

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of staked hay bales along the Woonasquatucket River. Photograph taken facing south.

FRAME NUMBER: 10 **DATE:** 15 September 1999

TIME: 15:25 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC100365



SCENE: View of floodplain area behind 41 Stevens Street, after Hurricane Floyd. Photograph taken facing west.

FRAME NUMBER: 11 **DATE:** 17 September 1999

TIME: 10:00 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC100365

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of installed chain-link fence at 562 Woonasquatucket Avenue. Note water level in Allendale Pond, after Hurricane Floyd. Photograph taken facing west.

FRAME NUMBER: 12 **DATE:** 17 September 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:05 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100365




SCENE: View of Allendale Pond, from 530 Woonasquatucket Avenue, after Hurricane Floyd. Photograph taken facing west.

FRAME NUMBER: 13 **DATE:** 17 September 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:10 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100365

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island




SCENE: View of Allendale Pond, from Allendale Dam. Note water levels, after Hurricane Floyd. Photograph taken facing north.

FRAME NUMBER: 14 **DATE:** 17 September 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:15 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100365

TOP



SCENE: View of clearing activities in Interim Cap No. 1 area, after Hurricane Floyd. Photograph taken facing south.


FRAME NUMBER: 16 **DATE:** 17 September 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 13:00 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100365

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island

TOP




SCENE: View of Centredale Manor parking lot, and cleared section (western edge) of Interim Cap No. 1. Photograph taken facing southwest.

FRAME NUMBER: 18 **DATE:** 23 September 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 13:00 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100365

TOP



SCENE: View of partially cleared section of Interim Cap No. 1, facing south. Photograph taken facing south.

FRAME NUMBER: 21 **DATE:** 23 September 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 13:05 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100365