

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island

TOP



SCENE: View of base fill being distributed in Interim Cap No. 1 area. Photograph taken facing southwest.

FRAME NUMBER: 17 DATE: 6 October 1999

TIME: 13:36 SKY CONDITION: Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta SETTING: Automatic

FILM TYPE: 35-mm FILM ROLL: BC300075



SCENE: View of base fill being delivered and distributed in Interim Cap No. 1 area. Photograph taken facing south.

FRAME NUMBER: 18 DATE: 6 October 1999

TIME: 13:40 SKY CONDITION: Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta SETTING: Automatic

FILM TYPE: 35-mm FILM ROLL: BC300075

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of tub grinder chipping tree trunks and larger size tree branches on site. Photograph taken facing south.

FRAME NUMBER: 19 **DATE:** 13 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 08:40 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300075




SCENE: View of tub grinder chipping tree trunks and tree debris on site. Photograph taken facing south.

FRAME NUMBER: 20 **DATE:** 13 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 08:42 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300075

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of tub grinder chipping tree trunks on site. Distribution of base fill continues. Photograph taken facing south.

FRAME NUMBER: 21 **DATE:** 13 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 08:45 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300075



SCENE: View of tub grinder chipping tree trunks on site. Photograph taken facing east.

FRAME NUMBER: 23 **DATE:** 13 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:45 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300075

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of tub grinder chipping tree trunks. Photograph taken facing east.

FRAME NUMBER: 24 **DATE:** 13 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:47 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300075



SCENE: View of geotextile liner being installed in Interim Cap No. 1. Note residential property in background. Photograph taken facing southeast.

FRAME NUMBER: 00 **DATE:** 19 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:45 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** 2155

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of geotextile liner being installed in the eastern section of Interim Cap No.1. Photograph taken facing southeast.

FRAME NUMBER: 0 **DATE:** 19 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:25 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** 2155



SCENE: View of geotextile liner being installed. Photograph taken facing south.

FRAME NUMBER: 01 **DATE:** 19 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:26 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** 2155

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of base fill being distributed in western section of Interim Cap No. 1. Photograph taken facing south.

FRAME NUMBER: 02 **DATE:** 19 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:27 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** 2155



SCENE: View of Emergency Rapid Response Services (ERRS) personnel installing geotextile liner on Interim Cap No. 1. Photograph taken facing south.

FRAME NUMBER: 03 **DATE:** 19 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:30 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** 2155

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of ERRS personnel installing geotextile liner on Interim Cap No. 1. Photograph taken facing south.

FRAME NUMBER: 04 **DATE:** 19 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:33 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** 2155




SCENE: View of base fill being delivered and staged in western section of Interim Cap No. 1. Photograph taken facing south.

FRAME NUMBER: 05 **DATE:** 19 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:34 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** 2155

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of final cover being distributed over the installed geotextile liner in Interim Cap No. 1. Photograph taken facing east.

FRAME NUMBER: 07 **DATE:** 19 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 13:17 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** 2155

TOP



SCENE: View of final cover being distributed over the installed geotextile liner. Photograph taken facing south.

FRAME NUMBER: 09 **DATE:** 19 October 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 14:21 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** 2155