

US EPA ARCHIVE DOCUMENT




FIGURE 4-1 PCE GROUNDWATER CONTAMINATION, 1991
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE




FIGURE 4-2 TCE GROUNDWATER CONTAMINATION, 1991
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE





FIGURE 4-3 CIS-1,2, DCE GROUNDWATER CONTAMINATION, 1991
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE



NOT TO SCALE




FIGURE 4-5 SHALLOW GROUNDWATER PLUME, PCE CONTAMINATION, JUNE 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SEDS PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE




FIGURE 4-6 SHALLOW GROUNDWATER PLUME, TCE CONTAMINATION, JUNE 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SEDS PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE




FIGURE 4-7 SHALLOW GROUNDWATER PLUME, DCE CONTAMINATION, JUNE 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SEDS PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE




FIGURE 4-8 TOP OF BEDROCK GROUNDWATER PLUME, TEMPORARY WELLS
PCE CONTAMINATION, JULY/AUGUST 1996
REMEDIAL INVESTIGATION REPORT
NORTH BELMONT PCE SUPERFUND SITE
NORTH BELMONT, GASTON COUNTY, NC
SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE




FIGURE 4-9 TOP OF BEDROCK GROUNDWATER PLUME (TEMPORARY WELLS and PERMANENT WELLS)
PCE CONTAMINATION, OCTOBER/NOVEMBER 1996
REMEDIAL INVESTIGATION REPORT
NORTH BELMONT PCE SUPERFUND SITE
NORTH BELMONT, GASTON COUNTY, NC
SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE