

US EPA ARCHIVE DOCUMENT




FIGURE 4-10 TOP OF BEDROCK GROUNDWATER PLUME (TEMPORARY WELLS and PERMANENT WELLS)
TCE CONTAMINATION, OCTOBER/NOVEMBER 1996
REMEDIAL INVESTIGATION REPORT
NORTH BELMONT PCE SUPERFUND SITE
NORTH BELMONT, GASTON COUNTY, NC
SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE




FIGURE 4-11 TOP OF BEDROCK GROUNDWATER PLUME (TEMPORARY WELLS and PERMANENT WELLS)
 CIS-1,2 DCE CONTAMINATION, OCTOBER/NOVEMBER 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE




FIGURE 4-12 BEDROCK GROUNDWATER PLUME (BEDROCK MW and POTABLE WELLS) NOT TO SCALE
PCE CONTAMINATION, OCTOBER/NOVEMBER 1996
REMEDIAL INVESTIGATION REPORT
NORTH BELMONT PCE SUPERFUND SITE
NORTH BELMONT, GASTON COUNTY, NC
SESD PROJECT No. 96S-058, JUNE 1997




FIGURE 4-13 BEDROCK GROUNDWATER PLUME (BEDROCK MW and POTABLE WELLS) NOT TO SCALE
TCE CONTAMINATION, OCTOBER/NOVEMBER 1996
REMEDIAL INVESTIGATION REPORT
NORTH BELMONT PCE SUPERFUND SITE
NORTH BELMONT, GASTON COUNTY, NC
SESD PROJECT No. 96S-058, JUNE 1997






FIGURE 4-14 BEDROCK GROUNDWATER PLUME (BEDROCK MW and POTABLE WELLS)
 CIS-1,2 DCE CONTAMINATION, OCTOBER/NOVEMBER 1996
 REMEDIAL INVESTIGATION REPORT
 NORTH BELMONT PCE SUPERFUND SITE
 NORTH BELMONT, GASTON COUNTY, NC
 SESD PROJECT No. 96S-058, JUNE 1997

NOT TO SCALE





1000

0

1000

2000 Feet

