

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/01/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 03/01/2012 – 0700, 03/08/2012
7. Personnel Roster Assigned				
Name		ICS Position		Contact Phone
Matthew Haak		Situation Unit		[REDACTED]
8. Activity Log				
Time	Major Events			
1100	<p>Helicopter safety briefing. Take off.</p> <p>Observations:</p> <ul style="list-style-type: none"> • Observed Timber Mats being staged off Division Street. • Talmadge Creek Staging area near MP0.75 observed area was demobilized and restored. • Timber mat road removed and restoration work observed near MP1.1 along Talmadge Creek. • Frac-City Soil Cells A & B. • Frac-City Soil Cells A & B. • Frac-City observed a Jon Boat being decontaminated. • Talmadge Creek near MP1.75 timber mats removed and restoration work observed. • Talmadge Creek turbidity control structure. • Overview of Talmadge Creek work. • Talmadge Creek near MP1.9 excavation work observed. • Talmadge Creek near MP1.9 excavation work observed. • Overview of Confluence work, observed sheet piling being installed. • MP2.75 RI crew observed. • OB8.97 I and OB9.10 LDB scrape locations. • OB8.97I sheen observed in scraped area. • OB10.37 RDB scrape location. • MP10.75 LDB flooding. • OB13.4 LDB excavation location. • Morrow Lake Delta. 			
1230	Touchdown at Marshall Field-complete daily over flight.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				