

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/02/2012	3. Time Prepared 1730
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 03/01/2012 – 0700, 03/08/2012
7. Personnel Roster Assigned				
Name		ICS Position		Contact Phone
Matthew Haak		Situation Unit		[REDACTED]
8. Activity Log				
Time	Major Events			
0900	<p>Observations:</p> <ul style="list-style-type: none"> • Observed Talmadge Creek Pump-around operating on south side of A Drive. • Observed Back-flow at A Drive culvert. • Observed Talmadge Creek Sediment trap removal activities. • Observed Talmadge Creek excavation work near MP1.85. • Observed Talmadge Creek restoration work near MP1.5. • Observed water management activities at turbidity control structure. • Observed snare absorbent within the turbidity control structure. • Observed Talmadge Creek sampling crew near MP1.85. • Observed Talmadge Creek bypass discharge turbidity monitoring. • Observed crews removing timber mats at Confluence. Sheen observed. • Observed Temperature effects study at Confluence house. • Talmadge Creek approximately MP1.9, crews observed sampling scrape area. • Observed Talmadge Creek excavation work near approximately MP1.9. 			
1500	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				