

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/06/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 03/01/2012 – 0700, 03/08/2012
7. Personnel Roster Assigned				
Name		ICS Position		Contact Phone
Matthew Haak		Situation Unit		[REDACTED]
8. Activity Log				
Time	Major Events			
0900	<p>Observations:</p> <ul style="list-style-type: none"> • Talmadge Creek: Turbidity Control Structure observed being demobilized. • Talmadge Creek: observed restoration work south of A Drive. • Talmadge Creek: observed restoration work near MP1.9. • Talmadge Creek: observed crews demobilizing pumps near MP1.9. • Talmadge Creek: observed crews demobilizing GAC system near MP1.85. • Confluence: observed sheet piling removed from area prior to excavation. • Confluence: observed SWAT observed boom prior to sheet pile installation. • Confluence: observed sheet piling installation at diversion structure discharge. • Confluence: observed crews removing super sacks from area to be excavated. • Confluence: observed central sheet piling at diversion structure discharge. • Talmadge Creek: observed water quality monitoring. • Confluence: turbidity observed. • Confluence: observed removal of the diversion structure. • Confluence: observed removal of the diversion structure culvert. • Confluence: observed removal of the diversion structure. • Confluence: sheen observed during the removal of the diversion structure. • Confluence: observed dewatering at diversion structure discharge. • Observed Temperature effects study. • Frac-City: observed vac-truck roll off emptied in to Cell A. • Frac-City: Observed Vac-Truck offloading GAC contents. • Frac-City: observed frac-tank being decontaminated. 			
1500	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				