

US EPA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill		03/8/2012	1725		
4. Unit Name/Designators		5. Unit Leader		6. Operational Period :	
Operations Unit/Overbank Branch, Recovery Group		Name:	Dan Capone & Joe Victory (START/US EPA)	From:	03/8/2012 0700
		Position:	Operations Section Chief	To:	03/8/2012 1725
7. Personnel Roster Assigned					
<u>Name</u>		<u>ICS Position</u>		<u>DUTY CELL</u>	
Dan Capone		Operations Section Chief			
Joe Victory		Operations Section Chief			
Rex Johnson		Director			
Dan Zahner		Field Team Lead			
Marc Wahrer		OBR Team #1			
8. Activity Log					
Activity Area				LAT	LAT
				Various (DD.MMMM)	Various (DD.MMMM)
<u>OIL OBSERVED</u>		<u>EXTENT OF OIL IMPACTED AREA</u>			
		<u>DENSITY OF OIL /SHEEN</u>			
Total Collection Points					
Total Boom Deployed					
Activity		<p><u>Weston/START Overbank Branch Recovery Group (OBR) Team Activity:</u> OBR-1: MP 9.10 surface scrap area</p> <ul style="list-style-type: none"> • Oversaw surface scrape activities at site MP 9.10. Ted Reckers (AECOM) EI, Chad Khodl (Superior) for sampling, Steve Runstrum (Enbridge OPS), Susan Jones (MDEQ) onsite. • Installed silt fence and temporary decon area at the MP 9.10 work area. • Started surface scrap work in the eastern end of the work zone area. Completed an area approximately 13'X20'. It was scraped to a depth of 2-3 inches and backfilled, seeded and covered with coconut blanket. • The area that was scraped showed no visual evidence of impact. No sheen or odors observed. One small tar patty was removed. • There was an area in the northwestern end of the work zone that we observed heavy sheen on the surface water where they had walked through to place the silt fence. It was back in the lower lying area at the base of the large hill (map in logbook). Dan Z and Matt (EPA/Weston) were also on site and observed the area in question. We notified Ted, Steve and showed Susan the impacted areas. • Ted and Steve said they completed and restored approximately 248 square feet. They removed 82 bags of soil and brought in 132 buckets of backfill soil. • Chad (Superior) collected one floor sample in the eastern scrape area that was completed. MDEQ did not collect a split. 			

Health and Safety Issues	
Comments	