

US EPA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill		03/12/2012	1715		
4. Unit Name/Designators		5. Unit Leader		6. Operational Period :	
Operations Unit/Overbank Branch, Recovery Group		Name:	Dan Capone & Joe Victory (START/US EPA)	From:	03/12/2012 0700
		Position:	Operations Section Chief	To:	03/12/2012 1715
7. Personnel Roster Assigned					
<u>Name</u>		<u>ICS Position</u>		<u>DUTY CELL</u>	
Dan Capone		Operations Section Chief			
Joe Victory		Operations Section Chief			
Rex Johnson		Director			
Dan Zahner		Field Team Lead			
Marc Wahrer		OBR Team #1			
8. Activity Log					
Activity Area				LAT	LAT
				Various (DD.MMMM)	Various (DD.MMMM)
<u>OIL OBSERVED</u>		<u>EXTENT OF OIL IMPACTED AREA</u>			
		<u>DENSITY OF OIL /SHEEN</u>			
Total Collection Points					
Total Boom Deployed					
Activity		<p><u>Weston/START Overbank Branch Recovery Group (OBR) Team Activity:</u> OBR-1: MP 9.10 surface scrap area</p> <ul style="list-style-type: none"> Oversaw surface scrape activities at site MP 9.10. Chad Khodl (Superior) for sampling and EI work today, Steve Runstrum (Enbridge OPS), Susan Jones (MDEQ) and Linda (JFNEW) onsite. Installed temporary decon area and temporary walkway at the MP 9.10 work area. Started surface scrap work in the next areas for the day. The areas completed today were scraped to a depth of 6 inches (in the 2-inch scrap area) and a section scraped to 12 inches to above water (in the 6 inch scrap area). The areas were backfilled, seeded and covered with coconut blanket. The area that was scraped to 12 inches had impacted soils to depth and we had to stop just above the water with the soils still impacted. The soils were still impacted and we observed some discolored soils, and sheen and some globules on the water seeping up into the scraped area. Steve said they completed and restored an area of approximately 240 square feet. They removed 343 bags of soil and brought in 460 buckets of backfill. <p>Chad (Superior) collected one floor sample from the far western scrap area of the work zone. The MDEQ did not collect any split samples.</p>			
Health and Safety Issues					
Comments					

--	--