

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/15/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 03/15/2012 – 0700, 03/22/2012
7. <b>Personnel Roster Assigned</b>				
<b>Name</b>		<b>ICS Position</b>		<b>Contact Phone</b>
Larry Rader		Situation Unit		[REDACTED]
8. <b>Activity Log</b>				
<b>Time</b>	<b>Major Events</b>			
0900	<p>Observations:</p> <ul style="list-style-type: none"> <li>• Observed crews conducting roadside/mailbox cleanup along residences on 15-1/2 Mile Road.</li> <li>• Talmadge Creek, observed restoration along creek west of 15-1/2 Mile Road.</li> <li>• Observed timber mats staged east of former Turbidity Control Structure location.</li> <li>• Observed crews removing last of timber mats at Former Turbidity Control System location.</li> <li>• Restoration work completed on Talmadge Creek south of A Drive, upstream from Confluence.</li> <li>• Talmadge Creek: additional straw bales staged on south side of creek.</li> <li>• Confluence, no sheen or turbidity issues observed.</li> <li>• Confluence, no activity observed in morning.</li> <li>• Confluence, crews installing new bridge across Talmadge Creek in afternoon.</li> <li>• Confluence, snare boom installed in culvert on south side of A Drive.</li> <li>• OB 9.10 LDB, scrape work continues.</li> <li>• Material staged along LDB for planned scrape at OB 10.37 RDB.</li> <li>• Historic Bridge Park, soil/water loading area for soils scraped from OB 9.10 LDB.</li> <li>• Frac Tank City cell A, cell is empty.</li> <li>• Frac Tank City Cell B, one roll-off box present.</li> <li>• Frac Tank City southern decon pad, observed crews cleaning a frac tank.</li> </ul>			
1500	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				