

US EPA ARCHIVE DOCUMENT

<b>1. Incident Name</b>		<b>2. Date Prepared</b>	<b>3. Time Prepared</b>	<b>UNIT LOG ICS 214</b>	
Kalamazoo River/Enbridge Spill		03/19/2011	1730		
<b>4. Unit Name/Designators</b>		<b>5. Unit Leader</b>		<b>6. Operational Period : DATE/TIME</b>	
Operations Unit, Environmental Compliance Branch, Overbank Recovery Team 2.		<b>Name:</b>	Joe Victory	<b>From:</b>	03/19/2011 0700
		<b>Position:</b>	Operations Section Dep	<b>To:</b>	03/19/2011 1730
<b>7. Personnel Roster Assigned</b>					
<b>Name</b>		<b>ICS Position</b>		<b>DUTY CELL</b>	
Daniel Zahner		Field Team Lead			
Tikvael Sulaiman		Overbank Team 2			
<b>8. Activity Log</b>					
<b>Activity Area</b>	MP 10.37	<b>LAT</b>	<b>LAT</b>		
		<b>Various</b>	<b>Various</b>		
		(DD.MMMM)	(DD.MMMM)		
<b><u>OIL OBSERVED</u></b>	<b>EXTENT OF OIL IMPACTED AREA</b>	N/A			
	<b>DENSITY OF OIL /SHEEN</b>	N/A			
<b>Total Collection Points</b>	NA				
<b>Total Boom Deployed</b>	NA				
<b>Activity</b>	<p><b><u>WESTON/START RECOVERY TEAM ACTIVITY</u></b></p> <p><b>Overbank Team 2</b></p> <p>Overbank Team 2 conducted oversight of shovel excavation at MP 10.73 as conducted by Enbridge, AECOM and SET crews.</p> <ul style="list-style-type: none"> <li>• Crew conducted hand/shovel excavation at MP 10.73. During excavation, areas that product was observed, crew excavated to 4 inches to remove product.</li> <li>• Excavated areas were then backfilled with clean soil and also seeded by JF New crew.</li> <li>• Total area excavated today is at 16x25 = 400sq ft.</li> <li>• Crew will continue tomorrow where they stopped today.</li> </ul>				
<b>Health and Safety Issues</b>	None				
<b>Comments</b>	The above information is summarized from Log book OBR-2.				