

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/21/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 03/15/12 – 0700, 03/22/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Demobilization of the staging area at the farmhouse on Division Drive appears complete.</li> <li>• Talmadge Creek/Source Area local activist observed.</li> <li>• Confluence, observed no turbidity or sheen.</li> <li>• Ceresco Dam, observed sweep boat.</li> <li>• Ceresco Dam, sheen observed flowing over spillway.</li> <li>• MP5.97, sheen and tar fleck observed downstream of Ceresco Dam.</li> <li>• MP7.0 LDB, overbank RI crew observed.</li> <li>• MP 8.8 RDB, overbank sheen observed in channel.</li> <li>• Scrape continuing at OB 8.97.</li> <li>• Scrape at OB 8.97, observed dewatering.</li> <li>• Scrape at OB 8.97, dewatering into tote on boat.</li> <li>• Historic Bridge Park soil staging area for the OB8.97.</li> <li>• Scrape work at OB10.37 continues.</li> <li>• MP14.75 C5 Boat Launch, sheen observed.</li> <li>• MP14.75 C5 Boat Launch, observed crew taking water and sediment temperatures.</li> <li>• MP27.5 observed sampling crews.</li> </ul>			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				