

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/22/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 03/22/12 – 0700, 03/29/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Confluence, observed poling along the boom and curtain.</li> <li>• Ceresco Dam, SWAT crew observed deploying boom.</li> <li>• Ceresco Dam, sheen collecting within boom.</li> <li>• OB10.37RDB, backfill being utilized.</li> <li>• OB10.37 RDB, scrape work continued.</li> <li>• OB10.37 RDB, restoration of scrape area.</li> <li>• OB8.97 I, scrape work continued.</li> <li>• Island A, tar globs and sheen observed.</li> <li>• Sheen observed RDB above Ceresco Dam.</li> </ul>			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				