

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/27/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 03/22/12 – 0700, 03/29/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	Operational status: - MP30.0 sheen observed at E4 boat launch. Sheen observed after boat was launched. - MP32.0 LDB during river assessment observed absorbent boom from last year submerged oil work was observed. SWAT disposed of boom. - MP32.0 sheen observed in center of river channel. - MP33.0 LDB former submerged oil location sheen observed.		
	Additional observations: None		
13:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			