

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/28/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 03/22/12 – 0700, 03/29/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
11:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> • Demobilization of the staging area at the farmhouse on Division Drive appears complete. • Frac-City observed foot print reduction. • Frac-City no decontamination activities observed. • Frac-City Soil Cells A & B. • Observed timber mat staged off Talmadge Creek near MP1.5. • Confluence, observed no turbidity or sheen. • Survey crew observed at Saylor's Landing. • MP2.5 LDB sheen observed. • MP2.75 RDB sheen observed. • Ceresco Dam observed newly installed boom. • OB8.97 crew observed. • MP10.5 SORT crew observed. • MP15.75 boom installed at the Battle Creek Spillway. • Morrow Lake, E4 Boom installed. 			
	Additional observations: None			
13:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				