


US EPA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill		03/29/2012	1800 Hours		
4. Unit Name/Designators		5. Unit Leader		6. Operational Period :	
Operations Unit/SORT		Name:	Dan Capone & Joe Victory (START/US EPA)	From:	03/29/2012 0700
		Position:	Operations Section Chief	To:	03/29/2012 1800
7. Personnel Roster Assigned					
Name		ICS Position		DUTY CELL	
Dan Capone		Operations Section Chief			
Joe Victory		Operations Section Chief			
Rex Johnson		Director			
Dan Zahner		Field Team Lead			
Sean Kane		SORT Team #4			
8. Activity Log					
Activity Area		Division E (Morrow Lake)		LAT	LAT
				Various	Various
				(DD.MMMM)	(DD.MMMM)
<u>OIL OBSERVED</u>		EXTENT OF OIL IMPACTED AREA			
		DENSITY OF OIL /SHEEN			
Total Collection Points					
Total Boom Deployed					
Activity		<u>Weston/START Shoreline and Overbank Reassessment Technique (SORT) Team Activity:</u> MP 39.75 LDB1 (Polygon) No oil/sheen identified MP 39.50 LDB1 (Polygon) No oil/sheen identified MP 39.25 RDB2 (Point) 2-points collected in Yuma for sheen 'film' on water. Sheen with oil globules noted at edge of wetland in Morrow Lake (Heavy, Heavy, Many) Apparently, oil globules rising from sediment in lake as boat rudder scraped bottom. MP 39.00 RDB1 No oil/sheen identified MP 39.25 RDB2 No oil/sheen identified MP 38.00 LDB2 No oil/sheen identified MP 37.75 LDB 1B No oil/sheen identified MP 37.75 LDB 1A No oil/sheen identified			

	MP 37.25 RDB1 No oil/sheen identified MP 37.50 RDB1 No oil/sheen identified
Health and Safety Issues	
Comments	