

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, April 2, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Larry Rader
START-USEPA
Situation Unit Leader



1. Crews setting up TARGOST equipment at C5.0 boat launch.



2. Close up of TARGOST sediment probe.



3. Crews deploying TARGOST probe near south end of Mill Pond.



4. Crews collecting sediment cores following TARGOST survey.



5. Onboard equipment for TARGOST technology.



6. Crews deploying the TARGOST probe near MP 14.97 RDB.



7. SORT crews surveying near MP 32.75 RDB.



8. SORT Crews near MP 32.75 RDB.



9. SORT crew No. 4 on island in Morrow Lake Delta.



10. SORT Crew No. 4 in Morrow Lake Delta.



11. E4 Containment boom in place.



12. Control Point E4 collection point.