

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 04/03/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 03/29/12 – 0700, 04/12/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Observed crews conducting TarGOST survey on upstream side of Ceresco Dam.</li> <li>• Observed chevron boom in place above Ceresco Dam.</li> <li>• Peninsula along LDB above Ceresco Dam. No sheen observed.</li> <li>• Collection point at C0.4 boat launch. No sheen, some minor debris observed in containment.</li> <li>• Containment boom downstream from Confluence. No sheen or turbidity observed.</li> <li>• Confluence. No sheen or turbidity observed.</li> <li>• Observed remote monitoring equipment on bridge at Confluence.</li> <li>• Containment boom in place at Confluence. No sheen or turbidity observed.</li> <li>• Frac tank city soil cells. One roll-off observed in Cell A and mat timbers observed in Cell B.</li> </ul>			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				