

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 04/10/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 03/29/12 – 0700, 04/12/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Confluence, observed sediment control structure. • SWAT crews observed deploying buoys at the Confluence. • SWAT crews observed deploying buoys across from the Confluence at a side channel. • Observed buoys deployed across from the Confluence at a side channel. • Observed SWAT crew deploying buoy east of 15 Mile RD just up from Saylor's Landing. • Observed SWAT crew deploying buoy at Saylor's Landing. • Observed crew deploying Walling Tubes upstream of the confluence. • Observed crew adjusting Walling Tube within the water column. • Observed crew deploying second Walling Tube at this location upstream of the confluence. • Observed new boom configuration above Ceresco Dam. • Observed crew reducing the foot print at the C0.4 boat launch. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				