

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, April 19, 2012

Kalamazoo River / Enbridge Spill

Prepared by:

Larry Rader
START-USEPA
Situation Unit Leader



1. Walling Tube with orange marker installed on Morrow Lake.



2. Morrow Lake poling crew in southern end of Morrow Lake.



3. RI sampling equipment staged for sampling near MP 12.0.



4. RI crews surveying near MP 12.00 RDB.



5. RI crews collecting soil samples near MP 12.00 RDB.



6. RI crews logging soil cores at C3.2 boat launch.



7. Soft shell turtles emerging from hibernation.



8. Turtles near MP 11.5.