

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, April 20, 2012

Kalamazoo River / Enbridge Spill

Prepared by:

Larry Rader
START-USEPA
Situation Unit Leader



1. Launch point for open river section. No boaters reported as of late morning.



2. Frac Tank City, crews continue to reduce footprint in northern end of area.



3. Frac Tank City soil cells A and B, no materials staged on cells.



4. Health & Safety reminder: be aware of agricultural vehicle traffic.



5. Debris and sheen in collection point above Ceresco Dam.



6. Collection point above Ceresco Dam.



7. Walling tube markers and buoys on river upstream from Confluence.



8. Close up of signs added to Walling Tube markers.



9. Crews testing new sheen sweep boat set up near C0.4 boat launch.



10. Crews testing new sheen sweep boat set up near C0.4 boat launch.



11. Crews unloading debris at C0.4 boat launch. Debris collected from Ceresco Dam containment point.



12. Bags of debris staged at C0.4 boat launch.