

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 04/23/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 04/19/12 – 0700, 04/26/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
11:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Observed launch point for open river section. River level has dropped since Friday.</li> <li>• Frac Tank City, crews continue to reduce footprint in northern end of area.</li> <li>• Frac Tank City soil cells A and B, no materials staged in cells.</li> <li>• Frac Tank City decon area. No activity observed.</li> <li>• Walling tube at Confluence. Creek water level has dropped since Friday.</li> <li>• Confluence. No turbidity or sheen observed. Creek and river levels have dropped since Friday.</li> <li>• Ceresco Dam. Crews staging equipment and beginning utility location for construction of access point below dam.</li> <li>• Observed boat crews removing debris from containment boom above Ceresco Dam.</li> <li>• Observed chevron Boom at Battle Creek spillway. No sheen or debris observed.</li> <li>• Morrow Lake. Poling crews shut down boat operations due to high winds on lake.</li> <li>• Control point at E4 boat launch. No sheen or debris observed.</li> </ul>			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				