

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Wednesday, April 25, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions from Yesterday (4-24-2012)

Conditions: Sunny, Clear, windy

Ambient Air Temperature High: 60° F

Average River Water Temperature: 52° F

Average River Sediment Temperature: 53° F



Prepared by:


Larry Rader
START-USEPA
Situation Unit Leader



1. Oil / sediment samples received from S. Hamilton (MSU), stored in refrigerator in house at Confluence. To be used for oil/sheen collection.



2. Oil/sediment samples from S. Hamilton (MSU) being thawed for oil/sheen collection.



3. Perrin Dam public access point. No public activity observed (photo taken yesterday 4-24-2012).



4. Source Area, no sheen observed (photo taken yesterday 4-24-2012).



5. Talmadge Creek. Water levels are lower, and exposed sand bars observed (photo taken yesterday 4-24-2012).



6. Frac-Tank City, footprint reduction continues (photo taken yesterday 4-24-2012).



7. Frac-Tank City, footprint reduction continues (photo taken yesterday 4-24-2012).



8. Frac-Tank City, materials observed along western wall of Cell B (photo taken yesterday 4-24-2012).



9. Frac-Tank City, no decontamination activities observed. (photo taken yesterday 4-24-2012).



10. Confluence. (photo taken yesterday 4-24-2012).



11. Saylor's Landing. No public activity observed (photo taken yesterday 4-24-2012).



12. C0.4 Boat Launch, one boat observed upstream from boat launch (Photos taken Tuesday 4-24-2012).



13. Ceresco Dam, no sheen observed (photo taken yesterday 4-24-2012).



14. Containment boom at Ceresco Dam (photo taken yesterday 4-24-2012).



15. C3.2 boat launch. Two boats observed at launch (photo taken yesterday 4-24-2012).



16. MP10.75, no sheen observed (photo taken yesterday 4-24-2012).




17. One boat crew observed near MP12.0 (photo taken yesterday 4-24-2012).



18. South end of Mill Pond. No sheen observed (photo taken yesterday 4-24-2012).



19. North end of Mill Pond (photo taken yesterday 4-24-2012).




20. Chevron boom at Battle Creek spillway. No sheen observed (photo taken yesterday 4-24-2012).



21. Crews collecting samples at RockTenn inlet (photo taken yesterday 4-24-2012).



22. RI crews observed near MP 24.0 (photo taken yesterday 4-24-2012).



23. RI crews observed near MP28.0 (photo taken yesterday 4-24-2012).



24. Boom installed near MP 30.8. No sheen observed (photo taken yesterday 4-24-2012).



25. Morrow Lake Delta (photo taken yesterday 4-24-2012).



26. East end of Morrow Lake Delta (photo taken yesterday 4-24-2012).



27. E4 Control Point. No sheen or debris observed (photo taken yesterday 4-24-2012).



28. Morrow Lake. Poling crews shut down due to high winds on lake (photo taken yesterday 4-24-2012).