

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 04/26/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 04/26/12 – 0700, 05/03/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Crews continue to reduce footprint at Frac Tank City. • Observed new buoy and sign configuration installed on open river section downstream from Confluence. • Observed water and sediment temperature data collection at Saylor’s Landing boat launch. • New containment boom configuration completed above Ceresco Dam today. • Sheen ribbons observed within containment above Ceresco Dam. • Ceresco Dam. Observed new boom Configuration along LDB above dam. • Observed chevron boom at Battle Creek Dam. • Observed RI crews collecting soil sample in overbank near MP 28.0 LDB. • Erosion control restoration work observed near MP 27.5 RDB. • Observed RI crews collecting soil samples near MP 24.0. • Observed soil sample collection near MP 24.0. • Observed groundwater sample collection near MP 23.75. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				