

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 04/27/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 04/26/12 – 0700, 05/03/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Observed crews building sediment collection devices for installation with sediment traps. • Crews continue footprint reduction at Frac Tank City. • Observed gravel removal in northern end of Frac Tank City. • Southern decon pad at Frac Tank City. Observed boom and materials staged in pad. • Observed crews conducting boom inspection and maintenance above Ceresco Dam. • Pond at former OB 5.92 RDB excavation location. Area inspected by Operations today. • Observed operations crews inspecting shoreline at MP5.92 LDB. • Observed former excavation site at MP 9.10. Area inspected by Operations today. • Observed former excavation location at MP 8.97. Area inspected by Operations crews today. • Observed Operations crew inspecting former 10.37 excavation area. • Observed restoration at former excavation area at MP 11.25 R2. Operations personnel inspected this location today. • Observed Operations personnel inspecting former excavation location at OB 13.40 RDB. • Observed sediment trap materials staged at former D2 boat launch, across the river from MP 19.25 LDB sediment trap location. • Observed crews off-loading materials for sediment trap installation at MP 19.25 LDB. • Observed crews continue poling activities in northeastern portion of Morrow Lake. • Control Point E4, no sheen observed. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				