

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 04/30/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 04/26/12 – 0700, 05/03/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • MP19.25, observed crews installing the sediment trap. • MP19.25, installed sediment trap. • MP19.25, sheen observed outside of boom. • Rock Tenn, sheen observed within the boom. • MP15.75, sheen observed within boom. • E4 Control Point, no sheen observed within the boom. • Sheen observed downstream of the E4 boom. • Sheen observed at the E4 boat launch • Sheen observed at E3 boat launch, sheen appeared when the boat agitated the sediment. • Observed crew poling in Morrow Lake Delta. • Legacy work continuing at Ceresco Dam. • Observed boom reconfigured at Ceresco Dam. • Confluence, sheen observed. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				