

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Wednesday, May 2, 2012


Kalamazoo River / Enbridge Spill

## Weather / River Conditions from Tuesday (5-1-2012)

Ambient Air Temperature High: 64° F

Average River Water Temperature: 57.46° F

Average River Sediment Temperature: 55.87° F



Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit Leader



1. MP10.75, observed crews installing the sediment trap.



2. MP10.75, observed crews installing the sediment trap.



3. MP10.75, observed crews installing the sediment trap.



4. MP10.75, sheen observed as crew installs the sediment trap.



5. Sediment collection devices to be installed at the sediment traps.



6. RI crew observed at MP10.0 LDB.



7. RI crew observed at MP10.0 LDB.



8. OB9.10, no sheen observed.




9. OB8.97, no sheen observed.



10. MP8.5 island tar patties observed.



11. Core logging.



12. Core sampling.