

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/03/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/03/12 – 0700, 05/10/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	Operational status: <ul style="list-style-type: none"> · MP37.75 Control Point E4, no sheen observed. · MP37.75, observed sheen sweep boat arriving at the E4 boat launch. · MP36.1, observed sediment control structure supplies staged near E4 boat launch. · Morrow Lake, observed poling crew 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				