

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/09/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/03/12 – 0700, 05/10/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	Operational status: <ul style="list-style-type: none"> <li>· Ceresco Dam control point boom, sheen observed along Ceresco Dam's boom.</li> <li>· MP5.63, sheen observed. Sheen tests were performed here.</li> <li>· MP5.63, jar test performed, oil stuck to jar lid.</li> <li>· Island A, sheen observed in pooled water.</li> <li>· Island A pooled water, sheen observed after walking through area.</li> <li>· OB2.75 RDB, sheen inspected and sheen tests performed.</li> <li>· Sheen sweep pontoon boat observed deploying out of C0.4.</li> <li>· MP5.25 RDB, sheen observed.</li> </ul>			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				