

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/10/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/10/12 – 0700, 05/17/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Observed pontoon sweep boat docked at E4. • Sheen observed around pom poms of sweep boat docked at E4. • Observed can buoys deployed at E4. • Observed buoys deployed within the Delta at E4. • Observed sheen sweep boat operating in Lake Morrow. • Observed Morrow Lake poling crew collecting a temperature reading. • Sheen sweep boat observed on the Delta side of E4 control point. • Ceresco Dam legacy work continued. • Ceresco Dam, sheen observed bubbling up and going over dam. • Frac-Tank City, footprint reduction work continued. • Frac-Tank City, observed crew transferring water in poly tanks. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				