

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/16/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/10/12 – 0700, 05/17/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Confluence from river. No sheen observed. • Observed poling crew near MP 2.25 just downstream from Saylor’s Landing. • Observed poling crews just downstream from C0.4 boat launch. • View from MP 5.75 RDB, looking downstream at Ceresco Dam. No sheen observed here today. • Observed poling crew near LDB upstream from Ceresco Dam. • Observed crews removing vegetation and debris from control point at Ceresco Dam. • Vegetation, debris, and sheen observed within control point above Ceresco Dam. • Oil globules and sheen within containment observed at Ceresco Dam control point. • Observed crews at C0.4 boat launch, loading debris removed from Ceresco Dam control point. • Former excavation site on Island at MP9.5. No sheen observed. • Observed crews inspecting sediment sample at 10.75 LDB sediment trap location. • MP 10.75 LDB sediment trap. No sheen observed along shoreline behind control point. • Observed tar globule and sheen within containment at MP 10.75 sediment trap. • Observed RI crews near MP 11.00 LDB. • Observed poling crews in back channel near MP12.50. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				