

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/17/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/17/12 – 0700, 05/31/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Poling crews and sheen sweep boat observed working upstream of Ceresco Dam. • Work completed at legacy site below Ceresco Dam. Crews observed demobilizing equipment from here today. • Control Point at Battle Creek spillway, no sheen or debris observed. • Observed crews filling sand bags at Rock Tenn inlet for planned inlet cleaning work. • Rock Tenn inlet. Sheen observed within containment. • Sheen observed within containment at Rock Tenn. • Observed mechanical area inside Rock Tenn inlet building. Location of planned confined space work. • Control Point E4, looking east into Morrow Lake Delta. No sheen observed. • Observed rews cleaning debris from E4 control point. • Poling crews observed along northern shore of Morrow Lake. • Morrow Lake Dam, no sheen observed. • South side of Morrow Lake Dam, no sheen observed. • Southwest corner of Morrow Lake. No sheen observed. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				