

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, May 21, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions for Monday (5-21-2012)

Conditions: Overcast

Ambient Air Temperature High: 74° F

Average River Water Temperature: 70° F

Average River Sediment Temperature: 68° F



Prepared by:

Larry Rader
START-USEPA
Situation Unit Leader



1. Source area pond, no sheen observed.



2. Frac-Tank City decon pad and soil cells. Boom observed in decon area.



3. Frac-Tank City, footprint reduction continues.



4. Confluence, no sheen observed.



5. Fishermen observed at Saylor's Landing.



6. MP4.5 LDB, Former Lily Pad area, sheen observed along bank and in Argo tracks. Inspection crews were notified.



7. Sheen observed along RDB downstream from C0.4 boat launch.



8. Sheen observed along RDB upstream from Ceresco Dam.



9. Control point above Ceresco Dam, sheen observed within containment.



10. Poling crew observed on Island near MP 8.0.



11. Sheen observed in inlet near MP 7.90 RDB. Inspection crews notified.



12. MP 10.75 LDB sediment trap, sheen observed within containment.



13. MP 11.25 peninsula, poling crews observed.



14. MP 11.75 LDB, sheen observed within containment.



15. MP 14.98 island, inspection crews observed on island.



16. Control point at Battle Creek spillway. Crews observed removing debris from boom.



17. Rock Tenn inlet, crews observed cleaning inlet inside containment.



18. Poling crew observed near MP 18.0.



19. Private pond at MP 26.25, sheen observed. Inspection crews notified.



20. MP 30.8, no sheen observed.



21. Morrow Lake Delta, sweeper boat observed along RDB.



22. Poling crew and sweeper boat observed upstream from E4 containment boom.



23. Morrow Lake Dam. One poling crew observed upstream from dam.



24. Poling crew mobilizing to new location below Morrow Lake Dam.



25. Bridge under construction downstream from Morrow Lake Dam.



26. Boat launch on Parcom Street below Morrow Lake Dam.



27. Poling crew operating below Morrow Lake Dam.



28. Morrow Lake Delta, sheen observed in southern portion of delta.