

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Friday, May 25, 2012

Kalamazoo River / Enbridge Spill


## Weather / River Conditions for Friday (5-25-2012)

Conditions: Sunny

Ambient Air Temperature High: 81° F

Average River Water Temperature: 70° F

Average River Sediment Temperature: 68° F



Prepared by:  
Timothy Laquerre  
START-USEPA  
Situation Unit Deputy



1. Sheen was not observed at the Rock Tenn Inlet



2. Collection Point at E-4 looking East at the Morrow Lake Delta.



3. Looking East at C5.0.



4. View of river downstream from Morrow Lake Dam. No sheen observed.



5. Looking upstream from C3.2 boat launch area.



6. Collection point at Ceresco Dam. Debris and sheen observed in containment.



7. Newly installed walling tube on the South side of A drive.