

US EPA ARCHIVE DOCUMENT

<b>1. Incident Name</b>	<b>2. Date Prepared</b>	<b>3. Time Prepared</b>	<b>UNIT LOG ICS 214</b>	
Kalamazoo River/Enbridge Spill	05/30/2012	1830		
<b>4. Unit Name/Designators</b>	<b>5. Unit Leader</b>		<b>6. Operational Period :</b>	
SOTF Team #6	<b>Name:</b>	Dan Capone & Joe Victory (START/US EPA)	<b>From:</b>	05/30/2012 1415
	<b>Position:</b>	Operations Section Chief	<b>To:</b>	05/30/2012 1800
<b>7. Personnel Roster Assigned</b>				
<b>Name</b>		<b>ICS Position</b>		<b>DUTY CELL</b>
Dan Capone		Operations Section Chief		
Joe Victory		Operations Section Chief		
Dan Zahner		Field Team Lead		
Kevin Johnson		SOTF#6		
<b>8. Activity Log</b>				
<b>Activity Area</b>	MP 37.50, 37.75 upstream of delta collection point.		<b>LAT</b>	<b>LAT</b>
			<b>Various</b>	<b>Various</b>
			(DD.MMMM)	(DD.MMMM)
<b><u>OIL OBSERVED</u></b>	<b>EXTENT OF OIL IMPACTED AREA</b>	NA		
	<b>DENSITY OF OIL /SHEEN</b>	NA		
<b>Total Collection Points</b>	NA			
<b>Total Boom Deployed</b>	NA			
<b>Activity</b>	<p><b><u>START SOTF Team 6 Activity:</u></b></p> <p>SOTF#6 Kevin Johnson (START), Enbridge Team Lead Loren Casale, and Leica operator Amber McDougal performed poling at 25 locations within focus areas 37.50 and 37.75 (central river delta upstream of collection point). A total of 6 locations had an overall submerged oil category of heavy, 11 locations had an overall submerged oil category of moderate, and 7 locations had an overall submerged oil category of light. One location had no signs of submerged oil.</p> <p>Generally, more light oil sheen was observed along areas of sand substrate with more moderate and heavy oil sheen, with corresponding globs up to 0.75cm, identified in locations having soft and silt based substrate.</p> <p>All locations SOTF #6 visited registered above the minimum temperature requirement of 60 degrees F. Observed temperatures ranged from 66.8 to 73.2 degrees F.</p> <p>Poling operations were not significantly impacted by vegetation within focus areas. Shallow water conditions did increase the difficulty of boat navigation in some areas. SOTF#6 was able to successfully navigate to all tasked poling reassessment locations.</p>			

<b>Health and Safety Issues</b>	None
<b>Comments</b>	Enbridge personnel conducted in field familiarization training during 11:00 to 14:00 for all new Team Leads (Loren Casale new Team 6 lead).