

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/01/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/31/12 – 0700, 06/07/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • MP26.25 RDB, sheen observed. • MP26.0 RDB, sheen observed. • MP25.75 RDB, poling crew observed. • MP21.5, observed crew sampling cylindrical sampling devices. • MP27.0 Shady Bend Campground, sheen observed around dock boats. • MP30.8, sheen observed within boom. • MP36.25, sheen observed within center of river channel. • MP36.5 LDB, sheen observed. • MP36.25, sweep boat responded to sheen observation. • Morrow Lake Delta, poling crew observed. • Morrow Lake, velocity data collection observed. • MP37.75, poling crew observed. • MP32.5 LDB, shore line erosion restoration observed. • MP28.25, cylindrical sampling device sampling observed. • MP28.0 LDB, sheen observed. • MP27.75, poling crew observed. • Ceresco Dam, sheen observed. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				