

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/05/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/31/12 – 0700, 06/07/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> • Source area pond, sheen observed. • Frac-Tank City, footprint reduction continues. • Frac-Tank City, no decontamination activities observed. • Confluence, no sheen or turbidity observed. • MP4.5 LDB, sheen observed in ARGOS tracks. • Ceresco Dam crew observed performing boom maintenance. • MP11.5, Poling crew observed. • MP11.5, crew continuing to remove woody debris from river. • MP14.0 LDB, overbank crew observed re-inspecting back channel. • MP15.65, Poling crew observed within the Mill Ponds. • MP20.5, Poling crew observed. • MP21.0 LDB, Poling crew observed. • MP21.5 Oxbow no sheen observed. • MP22.75, observed crew assessing overbank area. • MP26.0 Overbank pond, sheen observed. • MP26.25 Overbank pond, sheen observed. • MP26.25 RDB, sheen observed. • Sweep boat observed heading up river from Shady Bend Campground. • MP30.8, no sheen observed. • MP36.5 LDB, sheen observed. • Morrow Lake Delta, poling crew observed, sheen observed. • Morrow Lake Delta, sheen observed in Island. • Morrow Lake, observed velocity monitoring boat. • Morrow Lake, sediment plume observed. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				