

US EPA ARCHIVE DOCUMENT

<b>1. Incident Name</b>	<b>2. Date Prepared</b>	<b>3. Time Prepared</b>	<b>UNIT LOG ICS 214</b>	
Kalamazoo River/Enbridge Spill	06/06/2012	1840		
<b>4. Unit Name/Designators</b>	<b>5. Unit Leader</b>		<b>6. Operational Period :</b>	
SOTF Team #6	<b>Name:</b>	Dan Capone & Joe Victory (START/US EPA)	<b>From:</b>	06/06/2012 0900
	<b>Position:</b>	Operations Section Chief	<b>To:</b>	06/06/2012 1845
<b>7. Personnel Roster Assigned</b>				
<u>Name</u>		<u>ICS Position</u>	<u>CELL</u>	
Dan Capone		Operations Section Chief		
Joe Victory		Operations Section Chief		
Dan Zahner		Field Team Lead		
Kevin Johnson		SOTF#6		
<b>8. Activity Log</b>				
<b>Activity Area</b>	MP 30.00, 30.70, 30.80		<b>LAT</b>	<b>LAT</b>
			<b>Various</b>	<b>Various</b>
			(DD.MMMM)	(DD.MMMM)
<b><u>OIL OBSERVED</u></b>	<b>EXTENT OF OIL IMPACTED AREA</b>	NA		
	<b>DENSITY OF OIL /SHEEN</b>	NA		
<b>Total Collection Points</b>	NA			
<b>Total Boom Deployed</b>	NA			
<b>Activity</b>	<p><b><u>START SOTF Team 6 Activity:</u></b></p> <p>SOTF#6 Kevin Johnson (START), Enbridge Team Lead Loren CaSale, and Leica operator Amber McDougal performed poling at 12 total locations. A total of 1 location had an overall submerged oil category of heavy, 2 locations had an overall submerged oil category of moderate, and 8 locations had an overall submerged oil category of light. One (1) location indicated no signs of submerged oil.</p> <p>Generally, more light oil sheen was observed along areas of sand substrate with more moderate and heavy oil sheen observed along silt/soft substrate. Globules up to 0.5 cm were identified in locations having soft and silt based substrate.</p> <p>Nine (9) of the 12 locations SOTF #6 visited registered above the minimum temperature requirement of 60 degrees F. Observed temperatures ranged from 58.5 to 72.4 degrees F.</p> <p>Poling operations were not significantly impacted by vegetation or environmental conditions within focus areas. SOTF#6 was able to successfully navigate to all tasked poling reassessment locations.</p>			
<b>Health and Safety</b>	None			

<b>Issues</b>	SOTF6 experienced intermittent Leica operability during poling operations.
<b>Comments</b>	