

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/08/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/07/12 – 0700, 06/14/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
11:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> <li>• Source area pond, sheen observed.</li> <li>• Source area pond, reassessment crew observed.</li> <li>• Frac-Tank City, observed the timber mats being disposed of.</li> <li>• Island A sheen observed.</li> <li>• MP5.25 LDB, sediment plume and sheen observed.</li> <li>• Ceresco Dam, boom maintenance crew observed.</li> <li>• MP5.6 LDB, sheen observed.</li> <li>• MP5.63, sheen observed.</li> <li>• MP11.25R1, sheen observed.</li> <li>• MP13.25, Poling crew observed.</li> <li>• MP15.5 Mill Ponds, sweep boat observed.</li> <li>• MP15.75, boom maintenance crew observed.</li> <li>• MP19.25 sediment trap, sheen observed behind trap.</li> <li>• MP23.0 RDB, poling crew observed.</li> <li>• MP26.25 back channel, sheen observed.</li> <li>• MP28.25 oxbow, sheen observed.</li> <li>• MP30.8, no sheen observed within the boom.</li> <li>• MP33.75, Poling crew observed.</li> <li>• MP36.5, Poling crew observed.</li> <li>• Morrow Lake Delta, Poling crew observed.</li> <li>• E4, sediment plume observed.</li> <li>• Morrow Lake north shoreline, sweep boat observed.</li> <li>• Boom observed along south shoreline near the dam.</li> </ul>			
	Additional observations: None			
13:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				