

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/14/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/14/12 – 0700, 06/21/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Observed orientation and safety briefing for MAC members tour at C0.4 boat launch. • Observed sediment agitation demonstration with MAC members along left river bank above Ceresco Dam. • Observed sheen generated by agitation demonstration just above Ceresco Dam. • Observed sediment agitation demonstration near MP 5.65 RDB above Ceresco Dam. • Observed agitation test with MAC members near MP 4.0 LDB. • Observed sheen generated during agitation test with MAC members. • Observed debris removal along control point above Ceresco Dam. • Observed sheen sweep boat and debris removal at control point above Ceresco Dam. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				