

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Thursday, June 14, 2012

Kalamazoo River / Enbridge Spill


Weather / River Conditions for Thursday (6-14-2012)

Conditions: Sunny

Ambient Air Temperature High: 81° F

Average River Water Temperature: 70 ° F

Average River Sediment Temperature: 68 ° F



Prepared by:
Larry Rader
START-USEPA
Situation Unit Leader



1. Orientation and safety briefing for MAC members tour at C0.4 boat launch.



2. Sediment agitation demonstration with MAC members along left river bank above Ceresco Dam.



3. Sheen generated by agitation demonstration just above Ceresco Dam.



4. Sediment agitation demonstration near MP 5.65 RDB above Ceresco Dam.



5. Agitation test with MAC members near MP 4.0 LDB.



6. Sheen generated during agitation test with MAC members.



7. Debris removal along control point above Ceresco Dam.



8. Sheen sweep boat and debris removal at control point above Ceresco Dam.