1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214
Kalamazoo River/Enbridge Spill	06/15/2012	1800	

4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
SOTF Team #1	**Name:**	Dan Capone & Joe Victory (START/US EPA)	**From:**	06/15/2012 0800
	Position:	Operations Section Chief	**To:**	06/15/2012 1800

7. Personnel Roster Assigned

Name	ICS Position	DUTY CELL
Dan Capone	Operations Section Chief	████████
Joe Victory	Operations Section Chief	
Dan Zahner	Field Team Lead	
Jose Aguilera	SOTF#1	

8. Activity Log

			LAT	LAT
Activity Area	**MP24.50-33.0**		**Various**	**Various**
			(DD.MMMM)	(DD.MMMM)
OIL OBSERVED	**EXTENT OF OIL IMPACTED AREA**	NA		
	DENSITY OF OIL /SHEEN	NA		
Total Collection Points	NA			
Total Boom Deployed	NA			

Activity	**START SOTF Team #1Activity:** SOTF # 1 conducted oversight of Enbridge's Team A poling re-assessment activities. Team A collected 45 bathymetry points with GPS instrument including water depth. Data is downloaded into the hydrodynamic model. Team A also conducted poling activities at various areas that had failed the minimum temperature requirement. Team A recorded 15 poling locations. 1 point failed the minimum temperature requirement, no agitation conducted; however area has points that are classified as heavy sheen. 1 point classified as moderate, 4 points classified as light, 8 points with no visible contamination and 2 points located in dry areas.
Health and Safety Issues	None
Comments	None