


US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	06/15/2012	1759		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
SOTF Team #7	Name:	Dan Capone & Joe Victory (START/US EPA)	From:	06/15/2012 0700
	Position:	Operations Section Chief	To:	06/15/2012 1739
7. Personnel Roster Assigned				
Name	ICS Position		DUTY CELL	
Dan Capone	Operations Section Chief			
Joe Victory	Operations Section Chief			
Dan Zahner	Field Team Lead			
Marcus Muccianti	SOTF#7			
8. Activity Log				
Activity Area	Morrow Lake		LAT	LAT
			Various	Various
			(DD.MMMM)	(DD.MMMM)
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA	NA		
	DENSITY OF OIL /SHEEN	NA		
Total Collection Points	27			
Total Boom Deployed	NA			
Activity	<p><u>START SOTF Team # 2 Activity:</u></p> <p>Team SOTF #7 launched out of E4 and conducted poling ops. A total of 27 poling locations were assessed on Morrow Lake.</p> <p><u>Poling</u></p> <ul style="list-style-type: none"> • Morrow Lake: <ul style="list-style-type: none"> ○ M10 delineation results <ul style="list-style-type: none"> ▪ Total points: 26 with 0 none, 7 light, 19 moderate, 3 heavy ▪ All locations passed the temperature requirement ▪ Delineation of M10 is finished ○ Morrow Lake Monitoring Point Location Results <ul style="list-style-type: none"> ▪ Total point(s): 1 with 1 none, 0 light, 0 moderate, 0 heavy ▪ All locations passed the temperature requirement • At approximately 1300 AECOM joined our team to sample sheen at M10 <ul style="list-style-type: none"> ○ Sheen is to be fingerprinted 			
Health and Safety Issues	None			
Comments	Notes are in Logbook SOFT 7.			

