

US EPA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared		3. Time Prepared		UNIT LOG ICS 214		
Kalamazoo River/Enbridge Spill		06/18/2012		1900				
4. Unit Name/Designators			5. Unit Leader			6. Operational Period :		
SOTF Team #6			Name: Dan Capone & Joe Victory (START/US EPA)			From:		06/18/2012 0900
			Position: Operations Section Chief			To:		06/18/2012 1800
7. Personnel Roster Assigned								
<u>Name</u>			<u>ICS Position</u>			<u>DUTY CELL</u>		
Dan Capone			Operations Section Chief					
Joe Victory			Operations Section Chief					
Dan Zahner			Field Team Lead					
Hugh Murrell			SOTF#6					
8. Activity Log								
Activity Area		MP 29.83 to 28.54 and select spots.				LAT		LAT
						Various		Various
						(DD.MMMM)		(DD.MMMM)
<u>OIL OBSERVED</u>		EXTENT OF OIL IMPACTED AREA		NA				
		DENSITY OF OIL /SHEEN		NA				
Total Collection Points		NA						
Total Boom Deployed		NA						
Activity		<p><u>START SOTF Team 6 Activity:</u></p> <p>SOTF#6 Hugh Murrell (START), Tetra Tech Team Lead Kaylee ?, and Amber McDougle, from AECOM and Kenny our boat captain performed bathymetry poling at 78 locations within focus area 29.83 – 28.54. We noticed heavy sheen at mile post 28.77 after our boat was a bit stuck on a mud flat. After conversing with Joel Davis and Amber McDougle, Tetra Tech will try and put this area on a map with some points to delineate it properly.</p> <p>The weather was hot, approximately 93 degrees and we had a 2 hour safety stand down in the morning due to thunder and lightning.</p> <p>The reported moderate locations will be marked for later assessment by the Tetra Tech crews.</p>						
Health and Safety Issues		None						

Comments	