

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/19/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/14/12 – 0700, 06/21/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
11:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> • Frac-City: observed boom being decontaminated. • Confluence: no sediment or sheen observed. • MP5.0: Sweep boat observed. • Ceresco Dam: boom has been removed. • MP5.63: Observed crew removing vegetation. • Ceresco Dam: containment branch crew observed. • Ceresco Dam: portage work continued. • MP8.4: Boom removed. • MP8.45: Boom removed. • MP8.75: Reassessment crew observed. • MP8.9I: Reassessment crew observed. • MP11.75: Boom removed. • MP13.0: Sheen observed in river channel. • MP13.75: Reassessment crew observed in overbank area. • MP15.75: Boom observed being removed. • MP17.5: Poling crew observed. • MP27.75: sheen sweep boat observed. • MP28.25: Poling crew observed. • MP29.0: Reassessment crews observed. • MP33.0: Reassessment crew observed. • MP36.5: Reassessment team observed. • Morrow Lake Delta: sheen sweep observed at E4 boom. • Morrow Lake Delta: sheen observed. • Morrow Lake: poling crew observed. • Morrow Lake: velocity boat and sheen sweep boat observed. 			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				