

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/20/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/14/12 – 0700, 06/21/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, Texas
8. Activity Log				
Time	Major Events			
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Ceresco Dam: upstream portage observed being constructed.</li> <li>• Ceresco Dam: sheen and tar globs observed.</li> <li>• Ceresco Dam: sheen observed.</li> <li>• MP5.63: Observed crew removing vegetation from around trestles.</li> <li>• Ceresco Dam shoreline scrape work; sheen observed within sheet piling.</li> <li>• Ceresco Dam shoreline scrape work; sheen observed between sheet piling and curtain.</li> <li>• Ceresco Dam shoreline scrape work; worker cutting holes in bucket to drain water as it scrapes.</li> <li>• Ceresco Dam shoreline scrape work: soils being staged at Frac-City soil cells.</li> <li>• MP15.5 Mill Ponds: sweep boat observed.</li> <li>• MP17.0: Observed crew removing debris from river.</li> <li>• MP17.5: Observed poling crew.</li> <li>• MP34.5: poling crew observed.</li> <li>• MP36.0: observed reassessment team.</li> <li>• MP36.5: Observed reassessment team.</li> <li>• MP31.75: Observed reassessment team.</li> <li>• MP28.25 Oxbow: sheen observed.</li> </ul>			
	Additional observations: None			
15:00	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				