

US EPA ARCHIVE DOCUMENT

|  |  |  |                                |   |
|--|--|--|--------------------------------|---|
| <b>UNIT LOG</b>  |  | 1. Incident Name<br>Kalamazoo River/Enbridge Oil Spill                       | 2. Date Prepared<br>06/25/2012 | 3. Time Prepared<br>1700                                    |
| 4. Unit Name/Designators<br>Situation Unit   |  | 5. Unit Leader (Name and Position)<br>Melinda Luetke, Planning Section Chief |                                | 6. Operational Period<br>0700, 06/21/12 –<br>0700, 06/28/12 |
| 7. Personnel Roster Assigned   |  |  |                                |   |
| Name   |  | ICS Position   |                                | Home Base   |
| Matthew Haak   |  | Situation Unit Leader  |                                | Houston, Texas  |
| 8. Activity Log  |  |  |                                |   |
| Time   | Major Events   |  |                                |   |
| 09:00  | <p>Operational status:</p> <ul style="list-style-type: none"> <li>• Observed sheen sweep boat operating at Ceresco Dam.</li> <li>• Portage work continued at Ceresco Dam.</li> <li>• Observed sheen sweep boat operating near C5 boat launch.</li> <li>• Observed sheen sweep boat operating near MP5.5 LDB.</li> <li>• Observed RI Crew atMP8.75.</li> <li>• Observed crew installing curtain onto boom.</li> <li>• MP37. 5: Observed newly installed booms.</li> <li>• MP37.75: Observed crews installing anchor points.</li> <li>• Observed sheen sweep boat operating in the north cove of Morrow Lake.</li> <li>• Morrow Lake poling crew observed.</li> <li>• Observed sheen sweep boat operating on Morrow Lake.</li> </ul> |  |                                |   |
|  | Additional observations: None  |  |                                |   |
| 15:00  | Return to ICP.   |  |                                |   |
| 9. Prepared by (Name and Position)<br>Matthew Haak, Situation Unit Leader, USEPA-START |  |  |                                |   |